

FIRE RISK ASSESSMENT: *NJD Sports Injury Clinic* located at the above address

This Fire Risk Assessment has been produced in-line with the fire risk guidelines found in www.communities.gov.uk/fire

PREMISES:	NJD Sports Injury Clinic						
Originally Assessed:	Jan. 2005	Assessed By:	Mr. N.J. Dinsdale	Last Review:	Jan. 2012	Next Review:	Jan 2013
Groups of people involved and numbers involved:		<ul style="list-style-type: none"> • Therapists = 1 or 2 • Visiting patients = maximum of 3 at any time • Student placement = 1 at any time 					

HAZARDS	EXISTING CONTROLS	RISKS NOT ADEQUATELY CONTROLLED	RISK LEVEL
<i>Fire arising from:</i> <ul style="list-style-type: none"> • Electrical appliances • Sources of ignition • Storage of inflammable chemicals • Smoking 	<ul style="list-style-type: none"> • Annual inspection and PAT testing of appliances by qualified engineer. • Regular inspection of appliances and cables by resident therapists. • Mains system circuit breaker installed • No naked flames involved • Minimal fluids / chemicals used in clinic operation. • Those which are used (massage oil) are adequately stored. • Fire extinguisher (dry powder) situated in clinic. • Battery operated smoke detectors fitted. • No smoking area. 	NONE	LOW
Poor egress / lack of fire exits	The clinic operates on a system ' <i>by appointment</i> ' only. Therefore, names and numbers of people within the clinic premises are known at all times, thus, easily controllable. Egress is possible through 2 separate doors.	NONE	LOW

Signed: *Nick Dinsdale*

Date: 10.01.2012